

## 15% Bleach Storage Tanks

HETRON Epoxy Vinyl Ester Resins – Case History



### Location / Year

Bison Labs  
Buffalo, New York  
Installed in 2005

### Fabricator

Plas-Tanks Industries  
Hamilton, Ohio

### Service Conditions

15% Sodium hypochlorite at ambient temperature

### Fabrication

HETRON FR992 epoxy vinyl ester resin. Structural layer filament wound. Corrosion barrier = 150 mils thick, BPO/DMA cure system for the corrosion barrier and MEKP cure system for the structural portion. Post cured throughout.

### Technical Data

- Storage Tanks (3):  
11,000 gallons each

NOTICE : No freedom from any patent owned by Seller or others is to be inferred. Because use conditions and applicable laws may differ from one location to another and may change with time, Customer is responsible for determining whether products and the information in this document are appropriate for Customer's use and for ensuring that Customer's workplace and disposal practices are in compliance with applicable laws and other governmental enactments. Seller assumes no obligation or liability for the information in this document. NO WARRANTIES ARE GIVEN ; ALL IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE ARE EXPRESSLY EXCLUDED.



Ashland is committed to the continuous evolution of technology and service solutions that promote health, safety and environmental protection around the world. © Registered trademark and ™ trademark of Ashland Inc.  
\* Registered service mark of the American Chemistry Council, © 2009 Ashland  
<http://www.ashland.com>, <http://www.hetron.com>